

LOCAL NOTICE TO MARINERS

COASTAL WATERS FROM EASTPORT, MAINE TO SHREWSBURY, NEW JERSEY

WEEKLY SUPPLEMENT

INTERNET ADDRESS

HTTP://www.navcen.uscg.gov

Weekly supplemental editions contain new information only available following the monthly edition. NOTE: Chart corrections and Light List changes appear only once each. A complete listing of current discrepancies and temporary changes appear in the monthly issue, LNM 09/03. Subscription to this weekly publication is free. If you have questions about the LNM or wish to be on the mailing list, contact:

COMMANDER, FIRST COAST GUARD DISTRICT (oan)

408 Atlantic Avenue, Boston, Massachusetts 02110-3350 Internet Address: https://www.uscg.mil/d1/navinfo.htm Telephone (Day): 1-800-848-3942 To order LNM: Ext. 8351 24 Hour FAX: (617) 223-8073

Coast Guard's Customer Infoline (8:00 a.m. - 4:00 p.m.): 1-800-368-5647

Hearing im paired (TDD) 1-800 689-0816

All bearings are in degrees TRUE - All times are in Local Time unless otherwise noted.

NOTE: A vertical line in the RIGHT MARGIN of sections I, V, VI, VII indicates new information.

BROADCAST NOTICE TO MARINERS

The following Broadcast Notice to Mariners (BNM's) have been issued since last week:

First District	CG1- 0088	to	0100
Group Boston	BOS- 0064	to	0064
Group Long Island Sound	LIS- 0038	to	0038
Group Moriches	MOR- 0045	to	0046
Group New York	NEW - 0096	to	0099
Group Portland	POR- 0031	to	0034
Group Southwest Harbor	SWH- 0047	to	0048
Group Woods Hole	WHO-0126	to	0130

Light List Reference: ATLANTIC COAST, VOLUME 1, COMDTPUB P16502.1, 2002 Edition

I SPECIAL NOTICES This section contains information of Special concern to the Mariner.

NONE THIS WEEK

II DISCREPANCIES This section lists all discrepancies to Aids to Navigation reported and corrected since the last published list. A discrepancy is a change in the status of an aid to navigation that differs from what is published and or charted.

LNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
95	Fire Island Light	LT EXT	12352	CG1-0100-03	11/03
645	Lower Middle Ground Buoy 5	OFF STA	13324	SWH-0047-03	11/03
680	Narraguagus River Buoy 5	OFF STA	13324	SWH-0048-03	11/03
235	Upper Kennebec River Buoy 16	OFF STA	13298	POR-0033-03	11/03
495	Pitchpine Ledges Buoy 4	OFF STA	13290	POR-0034-03	11/03
3160	Billingsgate Shoal Lighted Bell Buoy 1	OFF STA/LT EXT	13246	WHO-0129-03	11/03
9645	Point Judith Pond Channel Buoy 26	OFF STA	13219	WHO-0130-03	11/03

24030	New Haven Harbor Channel LGB 1	OFF STA	12371	MOR-0038-03	11/03
29740	Patchogue Bay Entrance Lighted Buoy 1	OFF STA	12352	MOR-0036-03 MOR-0045-03	11/03
34865	Ambrose Channel Lighted Bell Buoy 10	LT DIM	12402	NEW-0099-03	11/03
34995	Liberty Island Lighted Gong Buoy 29	LT DIM	12334	NEW-0098-03	11/03
	, , ,				
DISCREPANCIES CO	DRRECTED		Chart	DNM	LNM
LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
650	Southwest Ledge Lighted Whistle Buoy 2	WATCHING PROPERLY	13215	WHO-0078-03	06/03
2645	Blue Hill Harbor Buoy 5	WATCHING PROPERLY	13316	SWH-0046-03	10/03
3630	Penobscot River Buoy 11	WATCHING PROPERLY	13309	SWH-0030-03	08/03
3655	Penobscot River Buoy 18	WATCHING PROPERLY	13309	SWH-0015-03	07/03
4325	Inner Ledges Buoy 6	WATCHING PROPERLY	13307	SWH-0039-03	10/03
4335	Camden Harbor Bell Buoy CH	WATCHING PROPERLY	13307	SWH-0038-03	10/03
4385	Haddock Ledge Buoy 2	WATCHING PROPERLY	13302	SWH-0040-03	10/03
12920	Plymouth Harbor Channel Buoy 11	WATCHING PROPERLY	13253	BOS-0064-03	11/03
13160	Billingsgate Shoal Lighted Bell Buoy 1	N/A SEE ABOVE	13246	WHO-0125-03	10/03
13280	Long Point Shoal Lighted Bell Buoy 3	WATCHING PROPERLY	13249	WHO-0124-03	10/03
13800	Chatham Roads Bell Buoy 3	WATCHING PROPERLY	13229	WHO-0068-03	06/03
13855 15475	Stage Harbor Entrance LBB SH Vineyard Haven Light 7	WATCHING PROPERLY WATCHING PROPERLY	13229 13233	WHO-0093-03 WHO-0127-03	06/03 11/03
15910	Ouicks Hole Entrance LBB 1	WATCHING PROPERLY	13230	WHO-0126-03	11/03
17800	East Passage Lighted Gong Buoy 7	WATCHING PROPERLY	13223	WHO-0128-03	11/03
21380	Twenty Six Foot Spot LBB 32A	WATCHING PROPERLY	12367	LIS-0036-03	10/03
22340	Niantic River Channel Buoy 10	WATCHING PROPERLY	13211	LIS-0037-03	10/03
26010	Cuban Ledge Lighted Buoy 2	WATCHING PROPERLY	12366	NEW-0078-03	08/03
26015	Eastchester Bay Shoal Lighted Buoy 4	WATCHING PROPERLY	12366	NEW-0086-03	10/03
26025	Eastchester Bay Channel Lighted Buoy 7	WATCHING PROPERLY	12366	NEW-0095-03	10/03
27775	Threemile Harbor Entrance LBB TM	WATCHING PROPERLY	13209	MOR-0022-03	06/03
27960	Shelter Island Sound North Ch LWB N	WATCHING PROPERLY	12358	MOR-0030-03	08/03
27965	Shelter Island Sound North Ch LBB 2	WATCHING PROPERLY	12358	MOR-0029-03	08/03
28040 28395	Shelter Island Sound North Ch LB 7 Shelter Island Sound South Ch Buoy 12	WATCHING PROPERLY	12358 12358	MOR-0041-03	10/03 10/03
29045	Shelter Island Sound South Ch Buoy 12 Shinnecock Inlet Lighted Buoy 4	WATCHING PROPERLY WATCHING PROPERLY	12358	MOR-0044-03 MOR-0025-03	07/03
30215	Narrows Bay Buoy 5	WATCHING PROPERLY	12352	MOR-0023-03 MOR-0031-03	08/03
30292	Moriches Bay Buoy 11	WATCHING PROPERLY	12352	MOR-0032-03	08/03
30335	Moriches Bay Buoy 26	WATCHING PROPERLY	12352	MOR-0014-03	05/03
30520	Tuthill Cove Buoy 4	WATCHING PROPERLY	12352	MOR-0021-03	06/03
36195	Princes Bay Range Rear Light	WATCHING PROPERLY	12331	NEW-0096-03	11/03
37055	New Jersey Pierhead Ch North Ent LB 6	WATCHING PROPERLY	12334	NEW-0097-03	11/03
DISCREPANCIES (PR	RIVATE AIDS)				
			Chart	BNM	LNM
LLNR	Name of Aid	Status	Affected	Ref.	Ref.
		NONE THIS WEEK			
DISCREPANCIES (PE	RIVATE AIDS) CORRECTED				
DISCREI ANCIES (I I	divate aids) corrected		Chart	BNM	LNM
LLNR	Name of Aid	Status	Affected	Ref.	Ref.
		NONE THIS WEEK			
		TOTAL TIME (TELLI			
	Y CHANGES - TEMPORARY CH				
	urrent week. When aids are temporarily reloca	neu for dredging, a temporary of	correction shall b	be fisted in Section IV giving	g the new position.
TEMPORARY CHAN	GES				
			Chart	BNM	LNM
LLNR	Name of Aid	Status	Affected	Ref.	Ref.
4450	Belfast Harbor Buoy 6	DISCONTINUED/DREDGE		CG1-0096-03	11/03
00000	Maine State Pier Mooring Buoy	DISCONTINUED	13292	CG1-0098-03	11/03
TEMPORARY CHAN	GES CORRECTED		CI.	DV3.4	LND
LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
4450 12685	Belfast Harbor Buoy 6	WATCHING PROPERLY	13309 13253	CG1-0486-02 CG1-0046-03	45/02 06/03
17300	Duxbury Bay Channel Buoy 22 Onset Bay Channel Buoy 1	WATCHING PROPERLY	13233	CG1-0046-03 CG1-0087-03	10/03
30365	Moriches Bay Lighted Buoy 29	WATCHING PROPERLY	12352	CG1-0005-03	02/03
30765	Shinnecock Bay Buoy 19	WATCHING PROPERLY	12352	CG1-0065-03	08/03
		The state of the s		- 3- 0000 00	- 27 **

This CHART IN CARRECT IN No. 1 and private maintained Aids to Navigation, as well as NOS corrections.

This section contains corrective actions affecting chart(s). Corrections appear numerically by chart number, and pertain to that chart only. The mariner must decide $\underline{which\ Chart(s)\ to\ correct}\ .\ The\ following\ example\ explains\ the\ individual\ elements\ of\ a\ typical\ chart\ correction.$

Chart Number ↓	Chart Edition ↓	Edition Date	Last Local Notice to Mariners	Horizontal Datum Reference	Source of Correction	Current Local Notice to Mariners
12327	91 st Ed.	04/19/97	LAST LNM 26/97	NAD 83	(CG1)	27/97
(TEMP) N	Y-NJ-NEW Y	ORK HARBOR	– RARITAN RIVER			
Δdd	National F	ock Channel Buo	v 3 green can		40°	41'09 0"N 074°02'48 1"W

1 Corrective Object of corrective Action Action

Local Notice to Mariners No. 11/03

Position (Degrees, minutes, seconds and tenths)

13/19/03

The letter (M) immediately following the chart number indicates that the correction should be applied to the Metric side of the chart only. (Temp) Indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (NM).

12300	42nd ed., 2/17/01 LAST LNM: 08/03 NAD 83	CGD01	11/03
CHANGE	APP NY TO FIVE FATHOM BANK Shinnecock Light from FL (2)R 15s to FL (2)W 15s	40-50-31.401N	072-28-41.677W
12327	96th ed., 11/13/02 LAST LNM: 09/03 NAD 83 NY - NJ - NEW YORK HARBOR - RARITAN BAY	CGD01	11/03
DELETE	Claremont Terminal Channel Danger Buoy A PTA 39/01	40-40-33.145N	074-03-33.000W
	Elizabethport Light	40-38-47.281N	074-11-20.089W
ADD	Elizabethport Directional Light, F WRG, 13M, 65 FT Black dashed line labeled RED From 40-38-47.300N 074-11-20.100W to	40-38-50.800N0	74-09-41.200W
	Black dashed line labeled WHITE from $403847.300\text{N}\ 0741120.100\text{W}$ to	40-38-49.100N	074-09-41.200W
	Black dashed line labeled RED from 40-38-47.300N 074-11-20.100W to	40-38-47.600N	074-09-41.200W
	Black dashed line labeled GREEN from 40-38-47.300N 074-11-20.100W to	40-38-45.900N	074-09-41.200W
	Claremont Terminal Channel Buoy 8 Red nun	40-40-44.094N	074-03-54.994W
RELOCATE	Claremont Terminal Channel Buoy 5 from 40-40-24.743N 074-03-29.445W to	40-40-24.577N	074-03-30.293W
	New Jersey Pierhead Channel North Entrance Lighted Buoy 6 from 40 -40-38.171N $074\text{-}03\text{-}28.307W$ to	40-40-31.472N	074-03-35.648W
	New Jersey Pierhead South Channel Lighted Buoy 13 from 40-39-55.117N 074-03-57.614W to	40-39-56.276N	074-03-58.816W
	New Jersey Pierhead South Channel Buoy 18 from 40-40-17.628N 074-03-38.918W to	40-40-17.360N	074-03-37.290W
12333	32nd ed., 10/1/02 LAST LNM: 07/03 NAD 83 NY - NJ - KILL VAN KULL AND NORTHERN PART OF ARTHUR KILL	CGD01	11/03
DELETE	Elizabethport Light	40-38-47.281N	074-11-20.089W
ADD	Elizabethport Directional Light, F WRG, 13M, 65 FT Black dashed line labeled RED From 40-38-47.300N 074-11-20.100W to	40-38-50.800N	074-09-41.200W
	Black dashed line labeled WHITE from 40-38-47.300N 074-11-20.100W to	40-38-49.100N	074-09-41.200W
	Black dashed line labeled RED from 40-38-47.300N 074-11-20.100W to	40-38-47.600N	074-09-41.200W
	Black dashed line labeled GREEN from 40-38-47.300N 074-11-20.100W to	40-38-45.900N	074-09-41.200W
RELOCATE	New Jersey Pierhead South Channel Lighted Buoy 13 from 40-39-55.117N 074-03-57.614W to	40-39-56.276N	074-03-58.816W
12334	65th ed., 1/1/03 LAST LNM: 06/03 NAD 83	CGD01	11/03
T 137	N 11/02		12/10/02

Page 3 of 14

$\ensuremath{\mathrm{NY}}$ - $\ensuremath{\mathrm{NEW}}$ YORK HARBOR - UPPER BAY AND NARROWS - ANCHORAGE CHART

DELETE	Claremont Terminal Channel Danger Buoy A PTA	40-40-33.145N	074-03-33.000W
ADD	Claremont Terminal Channel Buoy 8, Red nun to	40-40-44.094N	074-03-54.994W
RELOCATE	Claremont Terminal Channel Buoy 5 from 40-40-24.743N 074-03-29.445W to	40-40-24.577N	074-03-30.293W
	New Jersey Pierhead Channel North Entrance Lighted Buoy 6 from $40\mathcharpup$ 40-40-38.171N 074-03-28.307W to	40-40-31.472N	074-03-35.648W
	New Jersey Pierhead South Channel Lighted Buoy 13 from 40-39-55.117N 074-03-57.614W to	40-39-56.276N	074-03-58.816W
	New Jersey Pierhead South Channel Buoy 18 from 40-40-17.628N 074-03-38.918W to	40-40-17.360N	074-03-37.290W
12352	29th ed., 11/17/01 LAST LNM: 09/03 NAD 83 SHINNECOCK BAY TO EAST ROCKAWAY INLET	CGD01	11/03
CHANGE	Shinnecock Light from FL (2)R 15s to FL (2)W 15s	40-50-31.401N	072-28-41.677W
RELOCATE	Moriches Bay Lighted Buoy 29 from 40-47-12.775N 072-43-38.195W to	40-47-15.169N	072-43-30.483W
	Moriches Bay Buoy 26 from 40-47-07.456N 072-44-27.297W to	40-47-04.254N	072-44-19.590W
	Moriches Bay Buoy 27 from 40-47-05.025N 072-44-06.353W to	40-47-07.034N	072-44-00.978W
	Moriches Bay Buoy 17 from 40-46-44.409N 072-45-49.085W to	40-46-44.010N	072-45-49.274W
12353	17th ed., 6/13/92 LAST LNM: 49/00 NAD 83 SHINNECOCK LIGHT TO FIRE ISLAND LIGHT	CGD01	11/03
CHANGE	Shinnecock Light from FL (2)R 15s to FL (2)W 15s	40-50-31.401N	072-28-41.677W
12354	39th ed., 12/15/00 LAST LNM: 01/03 NAD 83 CT-NY-LONG ISLAND SOUND - EASTERN PART	CGD01	11/03
CHANGE	UCONN Oceanographic Lighted Buoy (ODAS) to UCONN Oceanographic Lighted Buoy (ODAS), Fl Y 4s, Yellow (Priv aid)	41-15-48.000N	072 <i>-</i> 04 <i>-</i> 00.000W
13003	46th ed., 1/1/03 LAST LNM: 04/03 NAD 83 ATLANTIC COAST - CAPE SABLE TO CAPE HATTERAS	CGD01	11/03
CHANGE	Shinnecock Light from FL (2)R 15s to FL (2)W 15s	40-50-31.401N	072-28-41.677W
13006	30th ed., 6/20/02 LAST LNM: 08/03 NAD 83 WEST QUODDY HEAD TO NEW YORK (LORAN-C)	CGD01	11/03
CHANGE	Shinnecock Light from FL (2)R 15s to FL (2)W 15s	40-50-31.401N	072-28-41.677W
13205	36th ed., 4/14/01 LAST LNM: 51/02 NAD 83 RI - CT - NY - BLOCK ISLAND SOUND	CGD01	11/03
ADD	UCONN Oceanographic Lighted Buoy (ODAS), Fl Y 4s, Yellow (Priv aid)	41-15-48.000N	072-04-00.000W
13212	35th ed., 12/2/02 LAST LNM: 04/03 NAD 83 APPROACHES TO NEW LONDON HARBOR	CGD01	11/03
ADD	UCONN Oceanographic Lighted Buoy (ODAS), Fl Y 4s, Yellow (Priv aid)	41-15-48.000N	072-04-00.000W
13221	53rd ed., 7/21/01 LAST LNM: 03/03 NAD 83 NARRAGANSETT BAY	NOS SILVER S	PRING 11/03
ADD	2 ft sounding at	41-44-45.400N	071-21-12.200W
CHANGE DELETE	note to: BULLOCK COVE The controlling depth in the entrance channel was 6 feet for a mid-width of 55 feet, with 5 feet in the south mooring basin; thence 4 feet to the north turning basin, with 2 feet available in the basin. Mar 2002 centered at 1 ft sounding at	41-46-20.000N0 41-44-31.500N	71-20-43.000W 071-21-15.000W

	2 ft sounding at	41-44-36.000N	071-21-13.200W
13224	36th ed., 12/1/01 LAST LNM: 06/03 NAD 83 PROVIDENCE RIVER AND HEAD OF NARRAGANSETT BAY	NOS SILVER SI	PRING 11/03
ADD	2 ft sounding at	41-44-45.400N	071-21-12.200W
	1 ft sounding at	41-45-13.100N	071-21-15.400W
CHANGE	depth legend to: 6FT MID 55 FT MAR 2002 at	41-44-30.000N	071-21-16.000W
	depth legend to: 4 FT 2002	41-45-01.000N	071-21-16.000W
DELETE	1 ft sounding at	41-44-31.500N	071-21-15.000W
13290	34th ed., 2/24/01 LAST LNM: 10/03 NAD 83 CASCO BAY	CGD01	11/03
CHANGE	Lighthouse Channel Buoy 1 to Lighthouse Channel Lighted Buoy 1, Fl G 6s, Green, $4M$	40-38-55.267N	070-15-02.913W
13292	35th ed., 3/4/00 LAST LNM: 47/02 NAD 83 ME - PORTLAND HARBOR AND VICINITY	CGD01	11/03
CHANGE	Lighthouse Channel Buoy 1 to Lighthouse Channel Lighted Buoy 1, Fl G 6s, Green, $4M$	40-38-55.267N	070-15-02.913W
13316	21st ed.,7/12/97 LAST LNM: 50/02 NAD 83 BLUE HILL BAY	CGD01	11/03
RELOCATE	Blue Hill Harbor Buoy 5 from 44-24-10.879N 068-33-39.422W to	44-24-11.376N	068-33-39.717W

V ADVANCE NOTICES This section contains advance notice of approved projects or upcoming temporary changes such as dredging, etc. Mariners are advised to use caution while transiting these areas.

ME/BELFAST HARBOR	30 April 2003	09/03
NY/NY STATE CANAL SYSTEM	27 June 2003	39/02
NEW ENGLAND	FY 03	32/02

NH - PORTSMOUTH TO DOVER AND EXETER - PISCATAQUA RIVER - The Coast Guard will be establishing a Coast Guard mooring on or about 12 April 2003:

Coast Guard Mooring, White buoy with Blue band, displaying "CG" in Black letters; in (PA) 43-06-40N, 070-48-11W. Establish Chart(s) 13285 LNM 11/03 (CGD1)

VI PROPOSED CHANGES

This section contains notice of non approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to: Commander, First Coast Guard District (oan), 408 Atlantic Avenue, Boston, MA 02110-3350, unless otherwise noted.

	PROPOSED W ATERWAY PROJECTS OPEN FOR PUBLIC COMMENT				
WATERWAY	Closing	Docket No.	Ref. LNM		
NY/SANDY HOOK CHANNEL	31 March 2003	01-03-04	10/03		

ME - HUNTINGTON BAY-The Coast Guard is considering making the following changes to Aids to Navigation in Huntington Bay.

Disestablish Sound signal at Eatons Neck Light (LLNR 21325). Disestablish Sound signal at Huntington Harbor Light (LLNR 26530).

Interested mariners are strongly encouraged to comment on this proposal in writing, either personally or through their organization. All comments shall be carefully considered and are requested prior to 30 June 2003 to facilitate the process. Refer to Docket No. 01-03-05. In addition to the address listed on the front cover, e-mail can be sent to: mrudick@d1.uscg.mil and faxes to (617) 223-8073.

Chart(s) 12363, 12364, 12365 LNM 11/03 (CGD1)

MA - BOSTON HARBOR - The Coast Guard is considering making the following change to Aids to Navigation in Boston Harbor.

Disestablish Sound signal at Gallops Island Light 7 (LLNR 11440).

Interested mariners are strongly encouraged to comment on this proposal in writing, either personally or through their organization. All comments shall be carefully considered and are requested prior to **30 June 2003** to facilitate the process. Refer to Docket No. 01-03-06. In addition to the address listed on the front cover, e-mail can be sent to: mrudick@d1.uscg.mil and faxes to (617) 223-8073. Chart(s) 13270, 13274 LNM 11/03 (CGD1)

VII GENERAL

This section contains information of general concern to the mariner. Mariners are advised to use caution while transiting these areas.

SUMMARY OF EFFECTIVE DREDGING/CONSTRUCTION OPERATIONS

GOLERY ERROLL

The following is a listing of marine construction and dredging projects still in effect in the First District. All mariners are advised to use caution in these areas. The LNM REF column refers to the LNM in which the article first appears and where detailed information may be obtained. The dates listed for completion are tentative. An asterisk in the left margin marks new information.

		COMPLETION	LNM
LOCATION	SUBJECT	DATE	REF
NY/JAMACIA BAY	Fender repairs	21 March 2003	06/03
NJ/NEWARK BAY	Marine construction	31 March 2003	49/02
NJ/SHREWSBURY RIVER	Marina renovations	31 March 2003	02/02
NY/RARITAN BAY	Dredging	31 March 2003	05/03
MA/DANVERS RIV; SALEM SOUND; BROAD SOUND;	Gas pipeline project	March 2003	48/02
NANTASKET ROADS; QUINCY BAY AND WEYMOUTH FORE	ERIVER		
NY/NJ/ARTHUR KILL	Pier demolition/construction	8 April 2003	41/02
ME/BELFAST HARBOR	Dredging	15 April 2003	44/02
NY/BROOKLYN	Pile/bulkhead repairs	April 2003	51/01
NY/LONG ISLAND SOUND	Pipeline construction	April 2003	37/02
MA/NEWBEDFORD	Bulkhead construction	30 April 2003	33/02
NJ/CLAREMONT CHANNEL	Dredging	31 May 2003	21/02
NY/LONG ISLAND/EAST RIV TO TALLMAN ISLAND	Pipeline construction	31 May 2003	45/02
NY/LONG ISLAND SOUND	Scientific research	12 June 2003	10/03
NJ/BAYONNE	Dredging	3 July 2003	49/02
NY/BROOKLYN	Piers constructions	September 2003	37/02
RI/PROVIDENCE RIVER AND HARBOR	Dredging	15 October 2004	09/03
NY/NY HARBOR/HUDSON RIVER	West Midtown Ferry Terminal Construction	November 2003	04/03
NJ/NEWARK BAY	Dredging	15 December 2003	47/02
NY/EAST RIVER	Constr of a temp FDR Dr.		
	and repairs to existing one	June 2004	34/02
US/SEACOAST	Cable laying	Until further notice	23/00
US/SEACOAST	Cable laying	Until further notice	46/00
MA/NANTUCKET SOUND/HORSESHOE SHOAL	Construction	Until further notice	40/02
MA/NANTUCKET SHOAL	Data tower Construction	Until further notice	41/02
MA/SALEM-MARBLEHEAD AND BEVERLY HBRS	Pipeline installation	Until further notice	43/02

NY – LONG ISLAND SOUND – Emergency cable repairs are being conducted north of Execution Rocks. The Weeks Crane Barge 540 will be held on station using a four point anchor spread, each anchor marked with a buoy and all around white light. The Tugs TREVOR and DOROTHY J are on-scene 24 hours/day through 3 April 2003 and may be contacted on VHF CH 13/16.

Chart(s) 12366 LNM 11/03 (CGD1)

NY – EAST RIVER – A 30'x90' spud barge with the Tug LITTLE C is in the east channel about 640' south of the Queensboro Bridge near the Brooklyn shoreline conducting test borings, Monday through Friday, 0700-1500, until **7 April 2003**. The Tug may be contacted on VHF CH 12/16. Chart(s) 12335 LNM 11/03 (CGD1)

BRIDGE SECTION					
Route 6 (Brightman St.)	В	Taunton River	1.8	New Bridge Construction	10-03
Longfellow Bridge	F	Charles River	1.5	Vertical Reduction	02-03
Chain Bridge	F	Merrimack River	5.8	Vertical Clear. Reduction	03-03
Summer Street	F	Reserved Channel	0.9	Bridge Construction	02-03
Route 88 Bridge	В	Westport River	1.2	Bridge Construction	52-02
I-95	F	Pequonock River	0.0	Bridge Replacement	09-03
Tomlinson	В	Quinnipiac River	0.0	Bridge Replacement	01-03
Route 1 (Singing)	F	Patchogue River	0.6	Bridge Rehabilitation	03-03
Sikorsky (Route 15)	F	Housatonic River	7.0	Bridge Rehabilitation	04-03
Manhattan Bridge	F	East River	1.1	Rehabilitation/Vert. Clear. Red	02-03
Williamsburg Bridge	F	East River	2.3	Bridge Rehabilitation	02-03
Triborough Bridge	F	East River	7.8	Deck Repl./Vertical Clear. Red.	09-03

.

Macombs Dam	SW	Harlem River	3.2	Bridge Rehabilitation	02-03
Spuyten Duyvil	SW	Harlem River	7.9	Fender Damaged	08-03
Third Avenue	SW	Harlem River	1.9	Bridge Replac./Channel Rest.	07-03
125 th Street	VL	Harlem River	1.3	Bridge Deck Replacement	02-03
Bear Mountain	F	Hudson River	46.7	Bridge Painting/Vert. Clear. Re-	d 08-03
Kingston-Rhinecliff	F	Hudson River	94.3	Deck Replacement	06-03
Tappan Zee	F	Hudson River	27.0	Bridge Painting/Scaffolding	01-03
Dutch Kills RR (DB)	SW	Dutch Kills	1.1	Bridge Closure	02-03
Beach Channel	SW	Jamaica Bay	6.7	Fender Repair	05-03
Beach Channel	SW	Jamaica Bay	6.7	Bridge Rehabilitation	11-03
Carroll Street	R	Gowanus Canal	2.0	Bridge Construction	04-03
Belt Parkway	F	Paerdegat Basin	0.2	Bridge Repairs	11-03
Verrazano	F	New York Harbor	0.0	Bridge Painting	02-03
Outerbridge Crossing	F	Arthur Kill	2.0	Bridge Piers Rehabilitation	02-03
Goethals	F	Arthur Kill	11.5	Sidewalk Repairs	02-03
Goethals	F	Arthur Kill	11.5	Bridge Painting/Scaffolding	08-03
Bayonne	F	Kill Van Kull	1.5	Bridge Rehabilitation	05-03
Route 1 & 9	VL	Hackensack River	1.8	Deck Replacement	02-03
NJ Turnpike	F	Newark Bay	4.0	Deck Repairs	10-03
Route 7	В	Passaic River	8.9	Bridge Replacement	09-03
Route 7	В	Passaic River	8.9	Fender Repair	11-03
Route 9	F	Raritan River	2.1	Bridge Replacement	05-03

\KEY: F-Fixed SW-Swing R-River C-Canal CK-Creek B-Bascule VL-Vertical Lift Ch-Channel Hbr-Harbor Th-Thoroughfare NM-Nautical mile.

APPLICATION HAS BEEN RECEIVED FOR COAST GUARD APPROVAL OF THE FOLLOWING BRIDGE DEVIATION AND REGULATION CHANGES:

WATERWAY/BRIDGE	MILE	33CFR Sect.	DEVIATION/RULE	EFF. DATE	REF/LNM
Glen Island/New Rochelle Harbor	0.8	117.802	Bridge Closure	12/1/02-4/1/03	48-02
Belt Parkway Br/Mill Basin	0.8	117.795	Bridge Closure	2/24/03-4/14/03	06-03
Route 1&9/Passaic River	1.8	117.739	Bridge Closure	3/12-4/2/03 & 4/12-5/10/03	09-03
Route 36/Shrewsbury River	1.8	117.755	Bridge Regulation Change	4/7/03	07-03
P.J. McArdle/Chelsea River	0.3	117.593	Advance Notice	3/9/03-4/7/03	10-03
Route 6/Taunton River	1.8	117.619	Bridge Closure	3/14/03-3/28/03	10-03

APPLICATION HAS BEEN RECEIVED FOR COAST GUARD PERMIT FOR THE FOLLOWING BRIDGES:

<u>BRIDGE</u>	WATERWAY	MILE	NOTICE#	COMMENT PERIOD	REF/LNM
Peconic Bay Blvd	Brushes Creek	0.0	PN 1-995	3 April 2003	08-03
Locust Ave (Rte 8A)	Claypit Creek	0.5	PN 1-993	3 April 2003	08-03
Patten Avenue Bridge	Manahassett Creek	0.2	PN 1-996	7 April 2003	10-03

NY – JAMAICA BAY AND ROCKAWAY INLET – BEACH CHANNEL - JAMAICA BAY – <u>Bridge Rehabilitation</u> – Two 60' X 100' Flexi Float Barges and work platforms will be located at various points in the waterway along the Beach Channel Swing Railroad Bridge and Viaduct across Jamaica Bay at mile 6.7. The work includes the structural rehabilitation of the Rockaway Viaduct connecting the swing bridge to land north and south. The normal operation of the swing bridge will not be affected. Mariners are advised to plan accordingly, reduce wake and exercise extreme caution when transiting the area. Chart 12350 LNM 11/03 (CGD1)

NY & NJ – NEW YORK HARBOR – HACKENSACK RIVER – Fender Repair – Fender repair to the Route 7 (Witt-Penn) Bridge across Hackensack River at mile 3.1 are ongoing. A spud barge measuring 92ft X 49ft, a scow barge measuring 30ft X 8ft, a 17ft Carolina skiff and 20ft utility boat will be operating in the waterway. Mariners are advised to exercise caution and reduce wake when transiting the area. Chart 12337 LNM 11/03 (CGD1)

NY – JAMAICA BAY – ISLAND CHANNEL – PAERDEGAT BASIN – <u>Bridge Repairs</u> – The substructure and fender system of the Belt Parkway Bridge across Paerdegat Basin at mile 0.2 has sustained damage possibly due to a barge allision. Repair work is in progress. Mariners are advised to exercise extreme caution when transiting the area.

Chart 12350 LNM 11/03 (CGD1)

VIII LIGHT LIST CORRECTIONS

An asterisk *, indicates the column in which a correction has been made or new information added.

(1) No.	(2) Name and location	(3) Position	(4) Characteristic	(5) Ht	(6) Rng	(7) Structure	(8) Remarks
515	Boston Approach Lighted Buoy BC	41-41-31N 69-35-23W	Fl Y 10s		6	Yellow.	
		*			*		11/03
560	Boston Approach Lighted	41-15-30N	Fl (4) Y 20s		7	Yellow.	Marked NOAA 44018.

	Buoy BB	69-17-40W *	0.5s fl 2.0s ec. 0.5s fl 2.0s ec. 0.5s fl 2.0s ec. 0.5s fl 2.0s ec. 0.5s fl 12.0s ec.				11/02
		Ŧ					11/03
565	Boston Approach Lighted Whistle Buoy BA	40-49-06N 68-59-58W *	Fl Y 10s		6 *	Yellow.	11/03
580	Nantucket Shoals Lighted Whistle Buoy N	40-30-09N 69-14-48W	Fl Y 6s		6	Yellow.	Racon: N ().
		*					11/03
675 29025	Shinnecock Light	40-50-31N 72-28-42W	Fl (2) W 15s 1.0s fl 2.0s ec. 1.0s fl 11.0s ec.	75	9	Red skeleton tower.	Horn: 1 blast ev 15s (2s bl)
760 35015	Shrewsbury Rocks Lighted Bell Buoy 1 Off east end of rocks.	40-20-28N 73-55-34W	Fl G 2.5s		4	Green.	11/03
		·					11/03
7710	Lighthouse Channel Lighted Buoy 1	43 38 54N 70 15 00W	Fl G 6s		4	Green.	
//10 -	*	70 13 00W	*		*	*	11/03
13565	- Lighted Bell Buoy 10	41-31-51N 70-00-31W *	Fl R 4s		4	Red.	Replaced by nun when endangered by ice.
13600	- Lighted Buoy 3	41-24-58N 69-48-26W *	Fl G 4s		4	Green.	Replaced by can when 11/03
13605	- Lighted Buoy 4	41-25-24N 69-49-27W *	Fl R 2.5s		4	Red.	Replaced by nun when endangered by ice.
1363	- Lighted Whistle Buoy GRC	41-24-21N 69-54-56W *	Mo (A) W		6	Red and white stripes with red spherical topmark.	11/03
13685	Cross Rip Lighted Gong Buoy 21	41-26-51N 70-17-30W *	Fl G 2.5s		4	Green.	11/03
							11/03
13690	Horseshoe Shoal Lighted Buoy 20 On south side of shoal.	41-27-33N 70-16-55W	Fl R 4s		4	Red.	Replaced by nun when endangered by ice.
		*					11/03
16000	Buzzards Bay Lighted Buoy 1	41-25-50N 71-02-16W *	Fl G 2.5s		4	Green.	11/03
16005	Buzzards Bay Lighted Bell Buoy 2	41-26-08N 71-00-39W *	Fl R 2.5s		4	Red.	11/03
16030	Buzzards Bay Lighted Gong Buoy 5	41-28-58N 70-57-22W	Fl G 6s		4	Green.	Removed when endangered by ice.
	Off southest side of ledge.	*					11/03
16035	Buzzards Bay Lighted	41-27-57N	Fl R 4s		4	Red	

	Bell Buoy 6	70-56-38W *					11/03
16050	Buzzards Bay Lighted Gong Buoy 8	41-28-57N 70-53-50W *	Fl R 2.5s	4	Red.		
16060	Buzzards Bay Lighted Gong Buoy 10 Marks western edge of	41-33-04N 70-46-39W	Fl R 4s	4	Red.	Replaced by LIB vendangered by ice	
	shoal.	*					11/03
16075	Buzzards Bay Obstruction Lighted Buoy 12	41-37-22N 70-42-19W	Q R	4	Red.	Removed when encice.	dangered by
	,	*					11/03
16080	Buzzards Bay Shoal Lighted Buoy 14	41-37-34N 70-42-01W *	Fl R 2.5s	4	Red.	Removed when end ice.	langered by 11/03
16105	- Lighted Buoy 1	41-37-50N 70-41-56W *	QG	4	Green.	Replaced by LIB vendangered by ice	when e. 11/03
21475	Sands Point Reef Lighted Buoy 25 Marks northwest edge of	40-52-07N 73-44-15W	Fl G 2.5s	3	Green.		
	shoal off point.	*					11/03
22011	New London SubBase Barrier		Fl W 4s	2	White and orange.	Private aid.	
	Lighted Buoy A		*	*		*	11/03
	New London SubBase Barrier		Fl W 4s	2	White and orange.	Private aid.	
Light	ed Buoy B		*	*		*	11/03
	New London SubBase Barrier		Fl W 4s	2	White and orange.	Private aid.	
Light	ed Buoy C		*	*		*	11/03
	New London SubBase Barrier		Fl W 4s	2	White and orange.	Private aid.	
Lignte	ed Buoy D *		*	*		*	11/03
	New London SubBase Barrier		Fl W 4s	2	White and orange.	Private aid.	
Light	ed Buoy E *		*	*		*	11/03
	New London SubBase Barrier ed Buoy F		Fl W 4s	2	White and orange.	Private aid.	
Ligito	*		*	*		*	11/03
22017	New London SubBase Barrier Lighted Buoy G		Fl W 4s	2	White and orange.	Private aid.	
	*		*	*		*	11/03
22018	New London SubBase Barrier Lighted Buoy H		Fl W 4s	2	White and orange.	Private aid.	
	*		*	*		*	11/03
22019	New London SubBase Barrier Lighted Buoy I		Fl W 4s	2	White and orange.	Private aid.	
22019.1	* New London SubBase Barrier		* Fl W 4s	* 2	White and orange.	* Private aid.	11/03
*	Lighted Buoy J	*	*	* *	*	*	11/03
22019.2	New London SubBase Barrier		Fl W 4s	2	White and orange.	Private aid.	

	Lighted Buoy K							
*	*	*	*	*	*	*	*	11/03
22019.3	New London SubBase Barrier Lighted Buoy L		Fl W 4s		2	White and orange.	Private aid.	
*	*	*	*	*	*	*	*	11/03
22019.4	New London SubBase Barrier Lighted Buoy M		Fl W 4s		2	White and orange.	Private aid.	
*	*	*	*	*	*	*	*	11/03
22019.5	New London SubBase Barrier Lighted Buoy N		Fl W 4s		2	White and orange.	Private aid.	
* 22010.4	* New London SubBase Barrier	*	* Fl W 4s	*	* 2	* White and orange.	* Private aid.	11/03
* *	Lighted Buoy O	*	**	*	*	*	*	11/02
		7.		*				11/03
	New London SubBase Barrier Lighted Buoy P		Fl W 4s		2	White and orange.	Private aid.	
*	*	*	*	*	*	*	*	11/03
22019.8	New London SubBase Barrier Lighted Buoy Q		Fl W 4s		2	White and orange.	Private aid.	
*	*	*	*	*	*	*	*	11/03
22019.9	New London SubBase Barrier Lighted Buoy R		Fl W 4s		2	White and orange.	Private aid.	
*	*	*	*	*	*	*	*	11/03
22019.	1 New London SubBase Barrier Lighted Buoy S		Fl W 4s		2	White and orange.	Private aid.	
*	*	*	*	*	*	*	*	11/03
22019.	2 New London SubBase Barrier		Fl W 4s		2	White and orange.	Private aid.	
*	Lighted Buoy T *	*	*	*	*	*	*	11/03
22019.	3 New London SubBase Barrier		Fl W 4s		2	White and orange.	Private aid.	
*	Lighted Buoy U	*	*	*	*	*	*	11/03
24045	- Channel Lighted Buoy 4	41-13-41N 72-54-44W *	Fl R 4s		4	Red.		11/03
24545	Bridgeport Harbor - Channel Approach Lighted Whistle Buoy BH	41-06-14N 73-11-44W	Mo (A) W		6	Red and white stripes with red spherical topmark.		
	•	*						11/03
25330	Little Captain Island East Reef Lighted Gong Buoy 1	40-59-36N 73-35-52W	Fl G 2.5s		4	Green.		
	Off east side of reef.	*						11/03
26865	Oyster Bay - Gong Buoy 1 On northwest side of Northwest Bluff Shoals.	40-55-33N 73-30-14W				Green.		
		*						11/03
34210	- Lighted Bell Buoy 2	40-31-46N 73-56-35W *	Fl R 4s		4	Red.		11/03
34945	Gowanus Flats Lighted	40-38-03N	Fl R 2.5s		4	Red.		

	Bell Buoy 22	74-03-02W *						11/03
34965	Gowanus Flats Lighted Bell Buoy 24	40-38-39N 74-03-14W *	QR		4	Red.		11/03
37033	- South Channel Lighted Buoy 13	40-39-56N 74-03-59W *	Fl G 4s		4	Green.		11/03
37055	- North Entrance Lighted Buoy 6	40-40-31N 74-03-36W *	Fl R 4s		4	Red.		11/03
37203	- Buoy 5	40-40-25N 74-03-30W *				Green can.		11/03
37208 *	Buoy 8	*	*	*	*	Red nun.	*	11/03
37355	ELIZABETHPORT DIRECTONAL LIGHT	40-38-47N 74-11-20W	F WRG	65	13	On skeleton tower on warehouse roof.	Shows red from 26 to 268.8; white from 268.8 to 269.2; gr from 269.2 to 270	om een
	*	*	*		*	*	*	11/03

Publication-National Ocean Service-U.S. Coast Pilot 1, Atlantic Coast: Eastport to Cape Cod, $2001\ (32^{nd}\)$ Edition. Change No. 25.

Coast Pilot 1 32nd Ed 2001

Corrections

Page 83-Paragraph 1498, insert after: §165.115 Safety and Security Zones; Pilgrim Nuclear Power Plant, Plymouth, Massachusetts.

(a) Location. All waters of Cape Cod Bay and land adjacent to those waters enclosed by a line beginning at position 41°57'05"N., 070°34'42"W.; then running southeast to position 41°56'40.5"N., 070°41'4.5"W.; then running southwest to position 41°56'32"N., 070°34'14"W.; then running northwest to position 41°56'55.5"N., 070°34'52"W.; then running northeast back to position 41°57'05"N., 070°34'42"W.

(b) Regulations. (1) In accordance with the general regulations in §§165.23 and 165.33 of this part, entry into or movement within these zones is prohibited

unless authorized by the Captain of the Port Boston.

(2) All vessel operators shall comply with the instructions of the COTP or the designated on-scene U.S. Coast Guard patrol personnel. On-scene Coast Guard patrol personnel include commissioned, warrant, and petty officers of the Coast Guard on board Coast Guard, Coast Guard Auxiliary, local, state, and federal law enforcement vessels.

(3) No person may enter the waters or land area within the boundaries of the safety and security zones unless previously authorized by the Captain of the Port, Boston or his authorized patrol representative.

(FR 5/30/02

Publication--National Ocean Service--U.S. Coast Pilot 2, Atlantic Coast: Cape Cod to Sandy Hook, 2001 (31st) Edition. Change No. 30.

Coast Pilot 2 31st 2001

Corrections

Page 94-Paragraph 2106, insert after: §165.115 Safety and Security Zones;

Pilgrim Nuclear Power Plant, Plymouth, Massachusetts.

- (a) Location. All waters of Cape Cod Bay and land adjacent to those waters enclosed by a line beginning at position 41°57'05"N., 070°34'42"W.; then running southeast to position 41°56'40.5"N., 070°41'4.5"W.; then running southwest to position 41°56'32"N., 070°34'14"W.; then running northwest to position 41°56'55.5"N., 070°34'52"W.; then running northeast back to position 41°57'05"N., 070°34'42"W.
- (b) Regulations. (1) In accordance with the general regulations in §§165.23 and 165.33 of this part, entry into or movement within these zones is prohibited unless authorized by the Captain of the Port Boston.
- (2) All vessel operators shall comply with the instructions of the COTP or the designated on-scene U.S. Coast Guard patrol personnel. On-scene Coast Guard patrol personnel include commissioned, warrant, and petty officers of the Coast Guard on board Coast Guard, Coast Guard Auxiliary, local, state, and federal law enforcement vessels.
- (3) No person may enter the waters or land area within the boundaries of the safety and security zones unless previously authorized by the Captain of the Port, Boston or his authorized patrol representative.

(FR 5/30/02)

Page 96-Paragraphs 2192 through 2196, read:

§165.160 Safety and Security Zones: Liquefied Hazardous Gas Vessel, Liquefied Hazardous Gas Facility and Designated Vessel Transits, New York Marine Inspection Zone and Captain of the Port Zone.

- (a) Location. The following areas
 are safety and security zones:
- (1) All waters of the New York Marine Inspection Zone and Captain of the Port Zone within a 200-yard radius of any Liquefied Hazardous Gas (LHG) vessel or LHG facility.
- (2) All waters of the New York Marine Inspection Zone and Captain of the Port Zone within a 100-yard radius of any Designated Vessels.
- (b) Designated Vessels (DVs). For the purposes of this section, DVs are: Local Notice to Mariners No. 11/03

- Vessels certificated to carry 500 or more passengers; vessels carrying government officials or dignitaries requiring protection by the U.S. Secret Service, or other Federal, State or local law enforcement agency; and barges or ships carrying petroleum products, chemicals, or other hazardous cargo.
- (c) Regulations. (1) The general regulations contained in 33 CFR 165.23 and 165.33 apply.
- (2) All persons and vessels must comply with the instructions of the Coast Guard Captain of the Port or the designated on-scene patrol personnel. These personnel comprise commissioned, warrant, and petty officers of the Coast Guard onboard Coast Guard, Coast Guard Auxiliary, local, state, and federal law enforcement vessels. Upon being hailed by U.S. Coast Guard patrol personnel by siren, radio, flashing light, or other means, the operator of a vessel shall proceed as directed.
- (3) The Captain of the Port will notify the maritime community of periods during which these zones will be enforced by methods in accordance with 33 CFR 165.7 and will identify DV vessel transits by way of electronic mail broadcast.

(FR 1/22/03)

Page 99-Paragraph 2356, line 3; read: proceed as directed.

§165.169 Safety and Security Zones: New York Marine Inspection Zone and Captain of the Port Zone.

- (a) Safety and security zones. The following waters within the New York Marine Inspection Zone and Captain of the Port Zone are safety and security zones:
- (1) Indian Point Nuclear Power Station (IPNPS). All waters of the Hudson River within 300-yard radius of the IPNPS pier in approximate position 41°16'12.4"N., 073°57'16.2"W. (NAD 83).
- (2) U.S. Coast Guard Cutters and Shore Facilities. All waters within 100 yards of: Each moored, or anchored, Coast Guard Cutter; Coast Guard Station New York; Staten Island, NY; Coast Guard Station Sandy Hook, NJ; Coast Guard Station Kings Point, NY; and Coast Guard Aids to Navigation Team New York,

Page 12 of 14 13/19/03

Bayonne, NJ.

- (3) Commercial Waterfront
 Facilities. All waters within 25 yards of
 each commercial waterfront facility that
 is capable of accepting barge, ferry or
 other commercial vessels. For purposes of
 this section, "commercial waterfront
 facility" means all piers, wharves, docks
 and similar structures to which barge,
 ferry or other commercial vessels may be
 secured; areas of land or water under and
 in immediate proximity to them; buildings
 on such structures or contiguous to them;
 and equipment and materials on such
 structures and in such buildings.
- (i) When a barge, ferry or other commercial vessel is conducting transfer operations at a commercial waterfront facility, the 25-yard zone is measured from the outboard side of the commercial vessel.
- (ii) Vessels may transit through any portion of the zone that extends into the navigable channel for the sole purpose of direct and expeditious transit through the zone so long as they remain within the navigable channel, maintain the maximum safe distance from the commercial waterfront facility and do not stop or loiter within the zone.
- (4) Liberty and Ellis Islands. All waters within 150 yards of Liberty Island, Ellis Island, and the bridge between Liberty State Park and Ellis Island.
- (5) Bridge Piers and Abutments, Overhead Power Cable Towers, Piers and Tunnel Ventilators. All waters within 25 yards of any bridge pier or abutment, overhead power cable tower, pier or tunnel ventilators south of the Troy, NY Locks. Vessels may transit through any portion of the zone that extends into the navigable channel for the sole purpose of direct and expeditious transit through the zone so long as they remain within the navigable channel, maintain the maximum safe distance from the waterfront facility and do not stop or loiter within the zone.
 - (6) New York City Passenger Ship

- Terminal, Hudson River, NY. (i) Location. All waters of the Hudson River bound by the following points: From the northeast corner of Pier 96 where it intersects the seawall, thence west to approximate position 40°46'23.1"N., 073°59'59.0"W., thence south to approximate position 40°45'55.3"N., 074°00'20.2"W. (NAD 1983), thence east to the southeast corner of Pier 84 where it intersects the seawall, thence north along the shoreline to the point of origin.
- (ii) Enforcement period. This zone will be enforced whenever passenger vessels are pierside at Pier 88, 90 or 92 or whenever the passenger ship terminal or the adjacent Intrepid Sea, Air and Space Museum, Manhattan is being used as an Emergency Operations Center. The activation and termination of a particular zone will be announced in accordance with 33 CFR 165.7.
- (b) Regulations. (1) The general regulations contained in 33 CFR 165.23 and 165.33 apply.
- (2) Vessels not actively engaged in legitimate transfer operations shall not stop or loiter within that part of a commercial waterfront facility safety and security zone extending into the navigable channel, described in paragraph (a)(3) of this section, without the express permission of the Coast Guard Captain of the Port or the designated onscene patrol personnel.
- (3) All persons and vessels must comply with the instructions of the Coast Guard Captain of the Port or the designated on-scene patrol personnel. These personnel comprise commissioned, warrant, and petty officers of the Coast Guard onboard Coast Guard, Coast Guard Auxiliary, local, state, and federal law enforcement vessels. Upon being hailed by U.S. Coast Guard patrol personnel by siren, radio, flashing light, or other means, the operator of a vessel shall proceed as directed.

(FR 1/22/03)

Publication–National Ocean Service–U.S. Coast Pilot 3, Atlantic Coast: Sandy Hook to Cape Henry 2002, (35th) Edition. Change No. 28.

Coast Pilot 3 35th Ed 2002

Page 124-Paragraph 160, line 5; read:

or sound apparatus may be inoperative. Landmarks ...

(NOS/03)

Page 132-Paragraph 39, lines 4-5, read: water and therefore are not charted. In August 2002, the controlling depth was 8.3 feet (10 feet at midchannel) in the entrance ...

(BP 179330)

Page 141-Paragraph 47, lines 4-7; read:

bridge, 0.4 mile from the mouth, has a bascule span with a 47-foot channel width and a vertical clearance of 14 feet. (See **117.1 through 117.59 and 117.705**, chapter 2, for drawbridge regulations.) The ...

(CL 1205/02)

Page 178-Paragraph 69, line 5; read:

had a midchannel controlling depth of 5 feet in October 2002. A repair ...

(BP 179707; CL 57/03)

Page 180-Paragraph 111, line 4; read:

with a controlling depth of 0.9 foot (1.3 feet at midchannel) in August 2002, extends about ...

(CL 59/03; BP 179710)

Page 186-Paragraph 116, line 6; read:

In September 2002, the midchannel controlling depth was 4.5 feet to ...

(CL 195/03; BP 179754)

Corrections

Page 201-Paragraph 71, lines 3-6; read: western arm about 0.8 mile above the entrance. In July 2002, the controlling depth was 4.5 feet in the E half of the channel with shoaling to 1.2 feet in the W half from the entrance to the turning basin, thence 9.8 feet in the basin. Depths of 10 feet are alongside the ...

(CL 61/03; BP 179713)

Page 202-Paragraph 88, lines 5-6; read:

45.3 miles above the Virginia Capes. **Stingray Point Light** (37°33'42"N., 76°16'23"W.), 34 feet above the water, is shown from ...

(25/02 CG5; LL/02)

Page 205-Paragraph 144, lines 4-5; read:

1990-September 2002, the controlling depth was 2.6 feet (3.4 feet at midchannel). An overhead power cable across the creek just above the ...

(CL 62/03; BP 179714)

Page 209-Paragraph 26, lines 1-4; read:

Smith Point Light (37°52'47"N., 76°11'01"W.), 52 feet above the water, is shown from a white square brick tower and octagonal dwelling on a brown cylindrical pier about 2.5 miles east-southeast of the point; a fog signal is at ...

(26/02 CG5; LL/02)

Page 238-Paragraph 58, line 1; read:

Tangier Sound Light (37°47'15"N., 75°58'25"W.), 45 feet

(25/02 CG5; LL/02)